



1) Attach the supplied mounting bracket to the ceiling or the floor, etc.




Tapping screw or
Machine screw with nut.



2) Adjust the angle of the monitor and fasten the screws firmly.



3) Install the sunshield (Optional)
4) Fix a sunshield into holes(6) and fitting it on the line of upper part, pull it down.



CAMERA CONTROLS



• CAMERA CONNECTOR



Pin No.	Description
1	Video Output
2	N/C
3	Audio Output
4	Power DC 12V
5	Ground